OUNTRY_	CLASSIFICATION CONTINUE OF THE	RECORDER PORT OF STREET
OPI <b>C</b>	Rangsdorf Airfield	
	25X1A 25X1A	AY
EVALUATION	PLACE OBTAINED	25X1A
OATE OF CO	0'	
DATE OBTAI	13 Tuno 1001	ayusa, sanado in remove - morto bellon e
EFERENCE		let are then desirable at the Area Area Area
AGES	1 ENCLOSURES (NO. & TYPE)	
,		Tagaca - Lagina agrandation and major commercia
1. K Societation to Indignations import in agreement		
25	25X1X	
SOURCE		panay agang unanggan apangahan ya
	the right side of the fuselage landed at Rangsdorf airfield and then taxied to the large Bucker Hangar. The plane came from the southeast. It took of again at 3:30 p.m. heading southeast. The plane was painted clive-drab, had a small superstructure on top of the fuselage behind the cockpit, a white rectangle on the radder assembly and a white No 6 on the upper section of the rudder assembly.  A biplane took off at 9:30 and another at 10 a.m. Both planes headed northwest. They landed again at 11:30 a.m. and 12:30 p.m. respectively. No special markings were seen on the planes. No other aircraft were observed at the field.	f d 25X1A
2.	The noise of machine tool engines was heard from the closed hangars. ** No aircraft crates were stored at the field. An aircraft salvage yard and at its side a fuel dump which was permanently guarded, were lecated in the northeastern corner of the field. Trucks heading the field.  25X1C	
25X1A   * **• <b> </b> 25X1A	Comment. The superstructure on the fuselage is probably a generator unit which feeds the radio equipment.  Comment. The airfield is not occupied by an air unit. It is believed that a repair shep for aircraft engines is housed in the hangars.	<b>i</b> ,
	CONFIDENTIAL	
Lo	CLASSIFICATION SECRET/CONTROL/US OFFICIALS ONLY	

